Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

 JK1319
 MANHOLE 36824
 NY LTANKS
 \$105057382

 ENE
 2900 OCEAN AVENUE
 NY Spills
 N/A

> 1 1.683 mi.

8886 ft. Site 1 of 2 in cluster JK

BROOKLYN, NY

 Relative:
 LTANKS:

 Higher
 Name:
 SATARA REALTY INC

 Actual:
 Address:
 2900 OCEAN AVENUE

 10 ft.
 City,State,Zip:
 BROOKLYN, NY

Spill Number/Closed Date: 9515460 / 2003-02-24

Facility ID: 9515460
Site ID: 197130
Spill Date: 1996-03-01
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: C3

Cleanup Ceased: Not reported SWIS: 2401 Investigator: TOMASELLO Referred To: Not reported Reported to Dept: 1996-03-01 CID: 266

Water Affected:

Spill Notifier:

Last Inspection:

Recommended Penalty:

Meets Standard:

UST Involvement:

Not reported

False

False

False

False

Date Entered In Computer: 1996-03-01
Spill Record Last Update: 2003-02-24
Spiller Name: JANET MATOS

Spiller Company: CASTLE OIL COMPANY
Spiller Address: 290 LOCUST AVENUE

0

Spiller County: 001

Remediation Phase:

Spiller Contact: JOSE REYAS
Spiller Phone: (718) 332-1506
Spiller Extention: Not reported

DEC Region: 2
DER Facility ID: 164083
DEC Memo: ""

Remarks: "DRIVER OVERFILLED TANK. ONTO CONCRETE IN REAR OF BUILDING.
CONTAINED. NEW YORK CITY DEP CONTACTED FOR CLEAN UP."

All Materials:

Site ID: 197130 Operable Unit ID: 1026565 Operable Unit: 01 Material ID: 355586 Material Code: 0003A #6 fuel oil Material Name: Case No.: Not reported Material FA: Petroleum Quantity: 50.00 Units: G .00 Recovered:

Oxygenate: Not reported

Map ID MAP FINDINGS

Direction Distance

EDR ID Number Elevation EPA ID Number Site Database(s)

SPILLS:

MANHOLE 36824 Name: Address: 2900 OCEAN AVENUE City, State, Zip: BROOKLYN, NY Spill Number/Closed Date: 0101720 / 2001-06-19

Facility ID: 0101720 Facility Type: ER DER Facility ID: 164083 196083 Site ID: DEC Region:

Spill Cause: Equipment Failure

Spill Class: C4 SWIS: 2401 2001-05-14 Spill Date: Investigator: **KMFOLEY** Referred To: Not reported Reported to Dept: 2001-05-15 CID: 216

Water Affected: Not reported Spill Source: Unknown Responsible Party Spill Notifier: Cleanup Ceased: Not reported Cleanup Meets Std: False Not reported Last Inspection: Recommended Penalty: False **UST Trust:** False

Remediation Phase:

Date Entered In Computer: 2001-05-15 Spill Record Last Update: 2001-08-31 Spiller Name: Not reported Spiller Company: UNKNOWN Spiller Address: Not reported Spiller Company: 001

Contact Name: TONY NATALE

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

> FOLEY CON ED E2MIS REPORT 5-14-01 Responding to a (21) MH fire in MH36824. no fir e/smoke was observed upon arrival. Found blown Primary Joint that looks to be on FDR 10B63. feeder will ahve to be verified by FOD. There was approx. 10ozs. of unknown oil on 1500gals. of water. no oil appears to be coming from the Blown Joint at this

time. Only oil filled equipment in structure is cable. 1 liquid sample taken. will begin cleanup as 50-499ppm 2355hrs. An earthen

sump foun in structure. Incident type will be changed from-spill deminimus to spill-oil (unknown) LSN 01-05651 <1.0pp 0400hrs. Cleanup completed by double washing structure with slix. 1300gals. of liquid waste removed by tanker, solids removed by vactor.blown Joint wrapped

by FOD. sump cemented. 5-16-01 1415hrs. No sign of burnout or

soot/smell of burnout."

"spill in manhole on top of 1500 gallons of water will be picked up Remarks:

pending results con edison ref # 137076 "

All Materials:

Site ID: 196083 Operable Unit ID: 840541 Operable Unit: 01 Material ID: 537425 Material Code: 0066A

Material Name: unknown petroleum Not reported Case No .: Material FA: Petroleum

Map ID Direction Distance

Site

Elevation

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

Quantity: 1.00 Units: G Recovered: .00

Oxygenate: Not reported